







## **BUILDING SPECIFICATIONS**

Structure	Generally reinforced concrete structure	Windows  Doors	Powder-coated aluminium-framed windows glazed with tinted glass
Wall Roof	Brick wall     Generally metal roofing		<ul> <li>Roller shutter to individual shops</li> <li>Glass door to main common entrances</li> </ul>
Ceiling Finishes	• Level 1 (Shop units) — Emulsion paint		Plywood flush door to others
	<ul> <li>to soffit of reinforced concrete slab</li> <li>Level 2 (Shop units) – plaster ceiling</li> <li>Toilets – asbestos-free cement boards</li> </ul>	Paintwork	<ul> <li>Internal walls – emulsion paint</li> <li>External walls – weatherbond paint (or equivalent)</li> </ul>
Wall Finishes	<ul> <li>Ceramic wall tiles to toilets (1.5m high)</li> <li>Plaster and quality paint finish to other areas (shop units)</li> </ul>	Plumbing & Sanitary	<ul><li> Quality sanitary fittings for toilets (Lot 1 and 14 only)</li><li> 1 no. of water point per unit</li></ul>
Floor Finishes	<ul> <li>Cement sand screed to individual shops</li> <li>Quality non-slip floor tiles to toilets</li> <li>Quality floor tiles to sidewalk and common area</li> </ul>	Electrical	<ul><li>Single phase power supply</li><li>Concealed wiring</li><li>Standard lighting and socket points</li></ul>



## **IBRACO BERHAD**

(011286-P)

(Exclusive marketing agent for Warisar Sdn Bhd)

**IBRACO HOUSE** No. 898, Jalan Wan Alwi, Tabuan Jaya, 93350 Kuching, Sarawak. Tel: 082-361111

BINTULU OFFICE No. 162, Lot 7787, Assyakirin Commercial Centre, 97000 Bintulu, Sarawak. Tel: 086-339098/339485 Email: sksim@ibraco.com For more information and to receive our latest updates! please contact:

086-339 098 (Bintulu) 086-339 485 (Bintulu) 013-837 5783 (Mr. Sim) 082-361 111 (Kuching)





Disclaimer: All illustrations and colour schemes are artist's impression only. The information contained herein is subject to change without notification as may be required by the relevant authorities or developers' architect and cannot form part of an offer or contract. All measurements are approximate. Whilst every effort has been made to ensure accuracy, the owner, developer and managers cannot be held responsible for any variations or inaccuracies.